



| | | | | | | | |
|--------|--------|---------------------------|--------|----|-------------------------|----------------------------|-------|
| 887821 | VPXJ10 | Connector Molex 194180013 | 10 46" | RD | 18 AWG Mag | Magnetometer | 9 |
| 879664 | VPXJ10 | Connector Molex 194180013 | 9 46" | BK | 14 AWG GND | 1/4" Ring Terminal | 'GND' |
| 849825 | VPXJ10 | Connector Molex 194180013 | 6 102" | RD | 18 AWG Swash1 | Amphenol C091-11H004-000-2 | 1 |
| 899876 | VPXJ10 | Connector Molex 194180013 | 1 70" | WH | 22 AWG #6 Ring Terminal | Starter Switch | 1 |

1. VPX J10 Connector: Molex 194180013 Terminals: 194200001 14-16AWG 194200002 18-22AWG
2. Swash1 Connector: Amphenol C091-11H004-000-2 Terminals: N010150047
3. Magnetometer Connector: DB-9 Male
4. Battery -: Connector: 1/4" Ring Terminal
5. Starter Switch: Connector: #6" Ring Terminal
6. Negative Bus Bar: 1/4" Ring Terminal